Workingmen's Houses,

Ann Morris House 358 Southern Avenue Dubuque Dubuque County Iowa HABS No. IA-159-BK

HABS 10VVA, 31-DUBU, 14-BK-

PHOTOGRAPHS HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
Department of the Interior
National Park Service
Rocky Mountain Regional Office
P.O. Box 25287
Denver Colorado 80225

Ann Morris House

14-BK-

HABS No. IA-159-BK

Site Location:

358 Southern Avenue

Dubuque, Dubuque County, Iowa

DOT designation: Resource Site No. 1.1 Cadastral grid : SW1/4 NE1/4 S36 T89N R2E USGS quadrangle: Dubuque South lowa 7.5' UTM coordinates: 15.691780.4705775

Lot dimensions: 35'x 20': .02 acre

Lot description: East 35' of Lot 1 of Lot 5

of O'Connor's Subdivision

Present Owner:

Iowa Department of Transportation

Present Usage: Present Condition: fair

vacant

Overall Dimensions: 1-1/2 story main block: 16'x 38'; front porch 16'x 4';

I-story rear addition: 16'x 12'.

Orientation:

northwest

Architectural Description:

Plan type: 1-1/2 story rectangle with rear addition.

Foundation: coursed limestone perimeter walls.

Structure : wood frame

Ext. walls: moderately exposed beveled wood siding, painted : front-gabled, moderately pitched; 3-tab asphalt Roofs

shingles on main block; asphalt roll roofing on

shed roof of rear addition.

: two corbeled brick interior chimneys, centered. Chimneys

Dormers

: none

Windows : wood 1/1 double hung sash; architraves around

> front windows, consisting of hood molds with a dentil course and decorative carving at ends; plain casings with hood molds and slip sills on other windows; awning windows on rear addition.

: primary entrance offset on front under the **Dpenings**

porch; (replacement) wood slab door with three stepped small windows with a decorative hood like those of the front windows; plain door on

the rear of rear addition.

Porches : full-width, open front porch; shallowly pitched

> hipped roof supported by 3 turned wood columns; unusual balustrade pattern includes vertical and staggered horizontal rails; diagonal wood

latticework surrounds porch crawl space.

Details : boxed cornices; bulkhead on northeast wall;

concrete steps with lead pipe railing lead up to property; picket fence, retaining wall.

Workingmen's Houses, Ann Morris House HABS No. IA-159-BK page 2

Construction Date: 1874

Architecture style: Gable ended box

Physical History: Teamster Morty D'Connor subdivided a portion of Mineral Lot 37 along Southern Avenue into residential lots in March 1868. A month later Ann Morris purchased Lot 5 from O'Connor for \$350. City directory evidence indicates that she built this two-story house and moved here from another residence on Dodge Street in 1874. A widow and a saloon worker, Morris lived in the house until selling it in 1879 to laborer Thomas Murray and his wife Ann. The Murrays in turn sold the property to N.J. Walker, who quit claimed it a year later to Charles P. Dillon. A blacksmith with the Iowa Iron Works and later a machinist for the Adams Company, Dillon lived here with his wife Bertha until the mid-192Ds. The property remained in the Dillon family until the late 1960s. Dver its extended occupation, the house has undergone few exterior alterations and retains a high degree of architectural integrity.

Significance: Similar in scale, configuration and materials to the other workingmen's houses built along Southern Avenue in the 187Ds and 1880s, the Ann Morris House is visually distinguished by its steep entry from the sidewalk. It is noteworthy for its excellent state of preservation. Historically, the house is typically associated with Dubuque's early proletariat.

References:

Dubuque City Directories: 1857 - 197D.

Dubuque County Assessment Record: 3-32-3-18.

lowa Department of Transportation, "Draft Environmental Impact Statement - Cultural Resources Assessment."

Land Title Abstract (located at Iowa Department of

Transportation, Ames Iowa).

Compiler:

Clayton B. Fraser, Fraserdesign, Loveland Colorado.

July 1988.